

RSL15 EVB Yellow Sticker Notice

Congratulations on the purchase of your RSL15 EVB.

In order to ensure adequate supply at launch, please be advised that a few RSL15 EVB Rev 1.1 boards were populated with an early version of the RSL15 device. These boards are marked with a yellow sticker on the underside, as shown below.

If you have received one of these boards, kindly note the following:

- The device may have sub-optimal receive sensitivity when buck mode is used
- Some calibration data may be missing from the calibration area in Flash
- It is recommended to operate the EVB only at room temperature



Learn more about RSL15 at the [onsemi Community Forums](#)