

*For additional information on our Pb ïFree strategy and soldering details, please download the onsemi Soldering and Mounting Techniques Reference Manual, SOLDERRM/D.

ſ

*This information is generic. Please refer to device data sheet for actual part marking. Pb ïFree indicator, "G" or microdot "," may or may not be present. Some products may